


<CONT3 board>



Fuse No.	Current (A)	Model	PART CODE	Silk	Related motor
F1	0.5	251.500	60200157	1/2A	AT guide motor
F2	1.0	251001	60200158	1A	Cutter motor
F3	0.125	251.125	60200156	1/8A	ND change motor
F4	0.5	251.500	60200157	1/2A	Front slack guide motor
F5	0.5	251.500	60200157	1/2A	Rear slack guide motor
F6	0.5	251.500	60200157	1/2A	Tension up/down motor

* All fuses are made by Ritel.